Fig. 1

e e

.

SAMPLE No.	FALL-DOWN TEST	PLANARITY	DIMENSIONAL ACCURACY DIMENSIONAL CHANGE FUSION STRENGTH AFTER MOLDING AFTER HEATING OF WINDOW	DIMENSIONAL CHANGE AFTER HEATING	FUSION STRENGTH OF WINDOW
1	УО	OK	УO	0	
2	УО	OK	УО	0	ΟĶ
3	УО) OK	УО	0	OK
4	УO	OK	УО	0	OK
5	УО	OK	УО	0	OK
9	УО	МО	OUT-OF-SPECIFICATION AT SOMEWHERE	0	OK
7	УО	OK	УО	0	OK

Fig. 2

CALL-DOWN TEST DIANA	I G	\ <u>\</u>	DIMENSIONAL ACCURACY	DIMENSIONAL CHANGE	FUSION STRENGTH
FALL-DOWN 1E31		וואאערוו	AFTER MOLDING	AFTER HEATING	OF WINDOW
УО		OK	OK	0	ı
OK	\vdash	OK	OK	0	OK
OK	_	OK	0K	0	УO
УЮ	\vdash	OK	OK	0	OK
УO		OK	OK	0	УО
УО		OK	-	0	OK
OK		OK	OK	0	ı
OK		OK	OK	0	OK
ЭOК		OK	OK	0	OK
OK		OK	OK	0	OK
OK		OK	OK	0	УO
OK		OK	_	0	OK
OK		OK	OK	0	1
OK		OK	OK	0	ОК
OK		OK	OK	0	OK
OK		OK	OK	0	OK
OK		OK	OK	0	OK
OK		OK	-	0	OK
OK		OK	OK	0	OK